

# HSS-CO



## HAND-GEWINDEBOHRER / HAND TAPS

KAT.-NR. ITEM	SIMBOL SYMBOL	Ø mm	DIN	SACKLOCH / DURCHGANGSLOCH Blind hole/ Through hole	TOLERANZ TOLERANCE	DRALLWINKEL HELIX ANGLE	ANSCHNITT FORM CHAMFER FORM
<b>VA</b>							
<b>6614</b>							
	M	2 ÷ 20	352		6HX	0°	C

<b>Ti</b>							
<b>6625</b>							
	M	2 ÷ 20	352		6HX	0°	C

## HSS-CO KURZE MASCHINEN-GEWINDEBOHRER / SHORT MACHINE TAPS

<b>N</b>							
<b>6678</b>	M	2 ÷ 20	352		6H	0°	C
<b>6659</b>	M	3 ÷ 20	352		6H	15°	C
<b>6639</b>	M	3 ÷ 20	352		6H	40°	C
<b>6604</b>	M	3 ÷ 24	352		6H-6G	40°	C
<b>6899</b>	MF	6 ÷ 20	2181		6H	0°	C
<b>6656</b>	MF	4 ÷ 24	2181		6H	15°	C
<b>6858</b>	BSP/G	1/16 ÷ 1-1/2	5157		-	0°	C
<b>6905</b>	BSP/G	1/8 ÷ 3/4	5157		<b>+0,1</b>	15°	C